Audit probe:

Bracket assembly, general notes follow.
1. Remove burrs and break sharp edges.
2. Finish: anodise clear, 10 um minimum.

Section 1 body text differs on each page x

DRAWING 4471-220
SHEET 1 OF 1
SCALE 1:1

Audit probe:

Bracket assembly, general notes follow.
1. Remove burrs and break sharp edges.
2. Finish: anodise clear, 10 um minimum.

Section 2 body text differs on each page y

DRAWING 4471-220
SHEET 1 OF 1
SCALE 1:1

Audit probe:

Bracket assembly, general notes follow.
1. Remove burrs and break sharp edges.
2. Finish: anodise clear, 10 um minimum.

Section 3 body text differs on each page z

DRAWING 4471-220
SHEET 1 OF 1
SCALE 1:1