Audit probe:

Bracket assembly, general notes follow.

1. Remove burrs and break sharp edges.
2. Finish: anodise clear, 10 um minimum.

PART	QTY	PRICE
Bracket	4	12.50
Bolt M6	16	0.40
Washer	16	0.05

DRAWING 4471-220
SHEET 1 OF 1
SCALE 1:1